

Proposal

www.sptpipe.com/CFC1428098/47-4731308

226 Field End St. Sarasota, FL 34240

Date:		

Bid #	ł
5669)

Job Information	Billing Information	
Baywood Colony	Name:	_
Name:	Address:	_
Address:		
	Phone:	_
Phone:	Email:	
Email:		

Reference: CCTV inspection/hydro-jet cleaning and CIPP lining

Specialized Pipe Technologies proposes the following option to Baywood Colony unit owners:

Option #1: CCTV inspection and hydro-jet cleaning on the sa	initary drains lines that service you	ur unit only.
Upon completion of cleaning, SPT will re-evaluate your syste	em to determine if CIPP lining is n	eeded.
Cleaning rates: \$20.00 per ft., minimum of 25'	Approved	Declined

Option #2: CIPP lining the sanitary drain lines that service your unit only.24 hrs after Option #1 completed.CIPP lining rates: \$60.00 per ft., minimum of \$25'ApprovedDeclined

These discounted rates are based on being approved within 24 hrs. of working in your unit grouping. If not approved within 24 hrs. but approved before substantial completion of the project, the rates increase to: Option #1: CCTV inspection and hydro-jet cleaning \$40.00 per ft., minimum of 25' Option #2: CIPP lining \$100.00 per ft., after Option #1 completed, minimum of 25'

Unit owner is responsible for the lines that service their units only. All shared/common lines are responsibility of the Association and will be cleaned/CIPP lined during the rehab project. **Upon substantial completion of the project, no discounted rates apply.**

ACCEPTANCE OF PROPOSAL AND AUTHORIZATION TO PROCEED

The above proposal is accepted and Specialized Pipe Technologies is authorized to proceed with the work as described and payment is hereby guaranteed as noted above. Please return fax signed authorization to 941-379-2160 or email to DeannaM@SPTpipe.com.

Date	Printed Name	
	-	

Authorized Signature ______

Specialized Pipe Technologies assumes no liability for any possible damage that could arise due to brittle, deteriorated, or cracked piping that could be uncovered by the hydro-cleaning process. If our equipment is hindered due to brittle, deteriorated or system layout & becomes necessary to open dig to retrieve, a change order may apply.